

Product:

Humidity control window

Application:

Indicator for checking the relative humidity within closed barriers. This moisture indicator window is used to check the condition of sensitive packaged goods by integrating it directly into barrier layers and flexible barrier films (PE or aluminum composite films).

Variants:

Art. No.	Indicator	Product dimensions (in mm – appr.)	PU / Subpackaged (in pcs)	Packaging Size (in mm – appr.)
635.001	30, 40, 50	116 x 116 x 20	12 / 60	400 x 300 x 320
635.002	40, 50, 60, 70, 80	116 x 116 x 20	12 / 60	400 x 300 x 320

PU = Packaging unit

Properties:

Component	Product feature	Value
Chemical characterization	Ingredients	635.001 Indicator window with Humidity Indicator card, contains cobalt dibromide, no dangerous ingredients
		635.002 Indicator window with Humidity Indicator card, contains cobalt dichloride
Packaging	Inner	PE-HD bag
	Outer	Corrugated cardboard box

Handling:

The respective display point (% relative humidity) changes from blue (dry) to pink (humidity range exceeded) as the humidity increases. The indicator is designed to be reversible and returns to blue when conditions are dry.

Note:

All information in this data sheet is intended to be of assistance to our customers. We exclude any obligations or warranty claims derived from the information published here. Changes of any kind may be carried out without special instructions. For the rest, we refer to our general terms and conditions, which can be found at www.thomar.de/english/toc.

2024 - ThoMar OHG

